

Technical Notice

Issue Date: Apr 11, 2017


Product Name:	Status:
IPX-13S-RS-R40	Running change

Reason for Change

Due to the EOL of PLX PCI6150-BB66PC

Description of Change

Add Pericom PI7C8150BMAE as the substitute of PLX PCI6150-BB66PC.



NOTE: IC replacement is unlikely to cause any problem in normal use. However, if any technical issues occur, please contact sales representatives or FAE immediately.

Affected by This Change
Specifications Dimensions Appearance Package Label BIOS Driver
For more details please refer to the latest datasheet or visit http://www.ieiworld.com.

www.ieiworld.com No.29, Zhongxing Rd., Xizhi Dist., New Taipei City 221, Taiwan (R.O.C.) Tel:886-2-8691-6798 Fax:886-2-6616-0028