

# Technical Notice

Issue Date: Apr 11, 2017

**Product Name:**

IPX-9S-RS-R41

**Status:**

Running change


## Reason for Change

Due to the EOL of PLX PCI6150-BB66PC


## Description of Change

Add Pericom PI7C8150BMAE as the substitute of PLX PCI6150-BB66PC.

**Before**



**After**



**NOTE:** IC replacement is unlikely to cause any problem in normal use. However, if any technical issues occur, please contact sales representatives or FAE immediately.

## Affected by This Change

Specifications  Dimensions  Appearance  Package  Label  BIOS  Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Issued date: 2014/08/22

# iEi Products Technical Notice



**Model Name: IPX-9S-RS-R41**

**R.E.: Terminal block 1\*8 DIP;180°;P:6.35mm;BLACK EOL**


**Solution: Remove the terminal block**

**Status: Running Change**

Dear Customers,

iEi appreciate your daily support on IPC business. Due to EOL of the terminal block 1\*8 DIP, iEi will remove the Terminal block 1\*8 DIP from IPX-9S-RS-R41.

You can refer to the figure1 for the difference between before and after removing the terminal block



Yours Faithfully  
John Lin  
Product Manager