

# Product Change Notification

**Issue Date:** November 23, 2017

**Product Name:** EBC-3100 & EBC-3000 Series

**Status:** Running change

## Reason for Change

Change ACE-A618A-RS-R11 to ACE-A618B-RS-R10 with EN 60950-1:A2 compliance.

## Description of Change

1. Change ACE-A618A-RS-R11 to ACE-A618B-RS-R10 with EN 60950-1:A2 compliance.
2. Change ACE-A627A-RS-R11 to ACE-A630B-RS-R10 with EN 60950-1:A2 compliance.
3. Minor power module bracket design modification for ACE-A618B-RS-R10 implement.

## Affected Model

| Affected Model         | New Version            |
|------------------------|------------------------|
| EBC-3100-R11           | EBC-3100-R12           |
| EBC-3100-R11/ACE-A627A | EBC-3100-R12/ACE-A630B |
| EBC-3100-R11/ACE-A618A | EBC-3100-R12/ACE-A618B |
| EBC-3000-R11           | EBC-3000-R12           |
| EBC-3000-R11/ACE-A627A | EBC-3000-R12/ACE-A630B |
| EBC-3000-R11/ACE-A618A | EBC-3000-R12/ACE-A618B |

## Affected by This Change

Specifications
  Dimensions
  Appearance
  Package
  Label
  BIOS
  Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>