

# Technical Notice

Issue Date: Aug. 11, 2021

**Product Name:**

Mustang-V100-MX8-R11

**Implementation Date:** Aug. 11, 2021

**Implementation Type:** Running Change


This notice is to inform you of changes to Mustang-V100-MX8 series

**Reason for Change**

PCB surface scratched by bracket.

**Description of Change**

Add two MYLARs which stick on bracket to avoid PCB surface damage



The implementation start from “SN Q214I20842”

**Affected Model**

Affected Model
Mustang-V100-MX8-R11

**Affected by This Change**

- Specifications       Dimensions       Appearance       Package  
 Certification       Label       BIOS       Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,*

*Brian Chen*

*Project Manager*

*IEI Integration Corp.*