Technical Notice

Model Name: iEi 945G series product

R.E.: Hardware reset function is only supported under Microsoft Windows environment for those 945G series products with the Intel® 45nm Core™ 2 Duo E7400 CPU.

Dear Customers,

iEi appreciates your daily support on IPC business.

Please note that the hardware reset function of the iEi 945G series with the Intel® 45nm Core™ 2 Duo E7400 CPU can only work well under Microsoft® Windows environment.

It is because the Intel® E7400 CPU is not officially supported with the Intel® 945G chipset.

This special support is made possible by iEi BIOS update.

The affected models are listed in the following table:

PICMG1.0	WSB-9454DVI-R11
	WSB-9454-R11
	WSB-9454DVI-R10
	WSB-9454-R10
ATX	IMBA-9454B-R10
	IMBA-9454ISA-R10
	IMBA-9454-R10
Micro-ATX	IMB-9454-R10
Mini-ITX	KINO-9454-R20

Yours Faithfully

Vicky Yen

Product Manager

http://www.iei.com.tw

IEI Technology Corp.

No.29, Chung-Hsing Rd.Shi Chi city, Taipei Hsien