# Product Change Notification

**Issue Date:** April 06, 2022

| | |
|---|---|
| **Product Name:** Mustang-V100-MX8-R11 | **Status:** Running change |

This notice is to inform you of changes to the Mustang-V100-MX8 series.

### Reason for Change

Universal Serial Bus 3.0 extended host controller IC will be EOL.

### Description of Change

Change Universal Serial Bus 3.0 extended host controller IC to new IC.

### Affected Model

| Affected Model | New Version |
|---|---|
| Mustang-V100-MX8-R11 | Mustang-V100-MX8-R20 |

### Affected by This Change

☐ Specifications  ☐ Dimensions  ☐ Appearance  ☐ Package
☐ Certification  ☐ Label  ☐ BIOS  ☐ Driver

For more details please refer to the latest datasheet or visit http://www.ieiworld.com.

*Best Regards,*

*Ting*

*Product Manager*

*IEI Integration Corp.*

**www.ieiworld.com**
No.29, Zhongxing Rd., Xizhi Dist., New Taipei City 221, Taiwan (R.O.C.)
Tel:886-2-8691-6798 Fax:886-2-6616-0028

ICP Deutschland GmbH | +49(0)7121-14323-20 | sales@icp-deutschland.de | www.icp-deutschland.de