

Technical Notice

Issue Date: Mar. 31, 2017

Product Name:

Implementation Date: 201/03/31

This notice is to inform you of changes to the below products.


Reason for Change

Due to the original dye vat is damaged after long term usage, our vendor change the new one for better quality.



Description of Change.

Heatsink color change from grass green to light green.

Original Color:



New Color:



Affected Model

34000-000291-RS for below products:

IMB-Q870-i2-R10
IMB-H110-R10
IMBA-C2360-i2-R10
IMBA-C2260-i2-R11
IMBA-H110-R10
IMBA-Q170-i2-R10
IMBA-Q170-ECO-R10
SPCIE-C236-R10
PCIE-Q870-i2-R10
SPCIE-C2260-i2-R10
PCIE-H810-R10
PCIE-Q170-R10
KINO-AQ170-R10
WSB-H810-R10

34000-000436-RS for below products:

NANO-HM650-R11
IMBA-C604EP-R10
IMBA-H610-R10
IMBA-Q770-R10

Affected by This Change

- | | | | |
|---|-------------------------------------|--|----------------------------------|
| <input type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
Elinor Chuang
Product Manager
IEI Integration Corp.*