

# Product Change Notification

**Issue Date:** April 7, 2015

<b>Product Name:</b> AFL-F08A-N270/R/1G-R24 AFL-F08A-N270/PC/1G-R24	<b>Status:</b> Running change
---	-------------------------------

This notice is to inform you of changes to the AFL-F08A-N270 series.

## Reason for Change

(1) Phase-out of Wireless IC/module, and change wireless IC from Ralink RT3090 to Atheros AR9485, Wireless driver is changed as well.

Phase-out Wireless IC	Replacement Wireless IC
<b>Ralink RT3090</b> (802.11 b/g/n, 1T1R, 2.4 ~ 2.5GHz)	<b>Atheros AR9485</b> (802.11 b/g/n, 1T2R, 2.4 ~ 2.5GHz)

(2) Phase out of Power Adapter

Phase-out Power Adapter	Replacement Power Adapter
<b>63000-FSP036RAB608-RS</b> FSP;FSP036-RAB;Vin:90~264VAC;36W; Vout:12VDC	<b>63040-010036-111-RS</b> FSP;FSP036-RBBN2;Vin:90~264VAC;36W; Vout:12VDC

## Affected Model

Affected Model	New Version
AFL-F08A-N270/R/1G-R24	AFL-F08A-N270/R/1G-R25
AFL-F08A-N270/PC/1G-R24	AFL-F08A-N270/PC/1G-R25

## Affected by This Change

Specifications
  Dimensions
  Appearance
  Package
  Label
  BIOS
  Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Marlene Lo

Project Manager

IEI Integration Corp.