

# Technical Notice

**Issue Date:** May 20, 2016

**Product Name:** FRK series

**Implementation Date:** May 20, 2016

This notice is to inform you of changes to the FRK12/15/17-R10 series.

## Reason for Change

Modified mechanism parts


## Description of Change

Modified mechanism parts to meet the EIA-310-D specification.


## Affected Model

Old Version	New Version
41020-0389C2-00-RS (for FRK12-R10)	41020-0389C2-01-RS


41020-0391C2-00-RS (for FRK15-R10)




41020-0418C2-00-RS



41020-0390C2-00-RS (for FRK17-R10)



41020-0431C2-00-RS



### Affected by This Change

- |   |  |                                     |                                  |
|---|--|-------------------------------------|----------------------------------|
| <input type="checkbox"/> Specifications | <input checked="" type="checkbox"/> Dimensions | <input type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification  | <input type="checkbox"/> Label                 | <input type="checkbox"/> BIOS       | <input type="checkbox"/> Driver  |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Henry Kao

Project Manager

IEI Integration Corp.