

# Technical Notice

Issue Date: Mar. 31, 2017

**Product Name:**

**Implementation Date:** 201/03/31

This notice is to inform you of changes to the below products.


## Reason for Change

Due to the original dye vat is damaged after long term usage, our vendor change the new one for better quality.



## Description of Change.

Heatsink color change from grass green to light green.

Original Color:



New Color:



#### Affected Model

34000-000291-RS for below products:

IMB-Q870-i2-R10  
IMB-H110-R10  
IMBA-C2360-i2-R10  
IMBA-C2260-i2-R11  
IMBA-H110-R10  
IMBA-Q170-i2-R10  
IMBA-Q170-ECO-R10  
SPCIE-C236-R10  
PCIE-Q870-i2-R10  
SPCIE-C2260-i2-R10  
PCIE-H810-R10  
PCIE-Q170-R10  
KINO-AQ170-R10  
WSB-H810-R10

34000-000436-RS for below products:

NANO-HM650-R11  
IMBA-C604EP-R10  
IMBA-H610-R10  
IMBA-Q770-R10

#### Affected by This Change

- |   |                                     |  |                                  |
|---|-------------------------------------|--|----------------------------------|
| <input type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification  | <input type="checkbox"/> Label      | <input type="checkbox"/> BIOS                  | <input type="checkbox"/> Driver  |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,  
Elinor Chuang  
Product Manager  
IEI Integration Corp.*