



# Product Change Notification

Issue Date: Aug 1, 2016

<p><b>Product Name:</b></p> <ol style="list-style-type: none"> <li>POC-W22A-H81i-P/PC/4G-R10</li> <li>POC-W22A-H81i-i3/PC/4G-R10</li> <li>POC-W22A-H81i-i5/PC/4G-R10</li> </ol>	<p><b>Status:</b> Implement immediately</p>	
<p>This notice is to inform you of changes to the POC-W22A-H81 <b>R10</b> series.</p>		
<p><b>Reason for Change</b></p> <ol style="list-style-type: none"> <li>Camera will be EOL.</li> <li>Solve ESD issue.</li> <li>Enhance OSD function.</li> <li>Improve details of design.</li> </ol>		
<p><b>Description of Change</b></p>		
<p><b>Item</b></p>	<p><b>R10 Version</b></p>	<p><b>R11 Version</b></p>
<p>Camera</p>	<p>7I002-AG5020B17S13T-RS</p>	<p>7I002-AG5020B27S23R-RS</p>
<p>ESD solution</p>	<p>--</p>	<p>Yes</p>
<p>OSD function</p>	<p>--</p>	<p>Yes</p>
<p>I/O bracket</p>	<p>RJ-11 port: through hole</p>	<p>RJ-11 port: <b>NON</b>-through hole</p>
<p>HDD bracket</p>	<p>Single screw hole</p>	<p>Dual screw hole</p>
<p>RFID</p>	<p>Original icon </p>	<p>New icon design </p>
<p>Front plastic cover</p>	<p>--</p>	<p>The gap between the front cover and the touch is smaller than the R10 version.</p>
<p>Cable cover</p>	<p>Standard</p>	<p>Optional</p>

**Affected Model**

Affected Model	New Version
POC-W22A-H81i-P/PC/4G-R10	POC-W22A-H81i-P/PC/4G-R11
POC-W22A-H81i-i3/PC/4G-R10	POC-W22A-H81i-i3/PC/4G-R11
POC-W22A-H81i-i5/PC/4G-R10	POC-W22A-H81i-i5/PC/4G-R11

**Affected by This Change**

- Specifications       Dimensions       Appearance       Package  
 Certification       Label       BIOS       Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,*  
*Chloe Mao*  
*Project Manager*  
*IEI Integration Corp.*