

Product Change Notification

Issue Date: April 21, 2015

Product Name: AFL-xxi-HM55 series	Status: Running change
---	-------------------------------

This notice is to inform you of changes to the AFL-xxi-HM55 series.

Reason for Change:

- (1) Phase-out of Wireless IC/module, and change wireless IC from Ralink RT5392L to Atheros AR9485, Wireless driver is changed as well.

Item	Phase-out Wireless Module	Replacement Wireless Module
IEI P/N	13ZSB71-00-101-RS	27303-000006-RS
Wireless IC	Ralink RT5392L (802.11 b/g/n, 2.4 ~ 2.5GHz)	Atheros AR9485 (802.11 b/g/n, 2.4 ~ 2.5GHz)

- (2) Phase out of Power Adapter

Item	Phase-out Power Adapter	Replacement Power Adapter
IEI P/N	63040-010096-010-RS	63040-010096-100-RS
Manufacturer's P/N	FSP;FSP096-DMAD1	FSP;FSP096-AHAN2
Specification	Vin:90~264VAC;96W;Vout:12VDC ;4Pin/lock	Vin:90~264VAC;96W;Vout:12VDC ;4Pin/lock

Affected Model

Affected Model	Replacement Model
AFL-15i-HM55-P45/R/1G-R20	AFL-15i-HM55-P45/R/1G-R21
AFL-15i-HM55i3-35/R/2G-R20	AFL-15i-HM55i3-35/R/2G-R21
AFL-15i-HM55i5-52/R/2G-R20	AFL-15i-HM55i5-52/R/2G-R21
AFL-15i-HM55i7-62/R/2G-R20	AFL-15i-HM55i7-62/R/2G-R21
AFL-17i-HM55-P45/R/1G-R12	AFL-17i-HM55-P45/R/1G-R13
AFL-17i-HM55i3-35/R/2G-R12	AFL-17i-HM55i3-35/R/2G-R13
AFL-17i-HM55i5-52/R/2G-R12	AFL-17i-HM55i5-52/R/2G-R13
AFL-17i-HM55i7-62/R/2G-R12	AFL-17i-HM55i7-62/R/2G-R13
AFL-19i-HM55-P45/R/1G-R20	AFL-19i-HM55-P45/R/1G-R21

AFL-19i-HM55i3-35/R/2G-R20
AFL-19i-HM55i5-52/R/2G-R20
AFL-19i-HM55i7-62/R/2G-R20

AFL-19i-HM55i3-35/R/2G-R21
AFL-19i-HM55i5-52/R/2G-R21
AFL-19i-HM55i7-62/R/2G-R21

Affected by This Change

Specifications Dimensions Appearance Package Label BIOS
Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Marlene Lo

Project Manager

IEI Integration Corp.