

Product Change Notification

Issue Date: May 13, 2015

Product Name: HPE-4S2-R40	Status: Running change				
Reason for Change Fix AT power mode issue.					
Description of Change Modify the schematic of 3.3V power.					
Affected Model					
<table border="1"><thead><tr><th>Affected Model</th><th>New Version</th></tr></thead><tbody><tr><td>HPE-4S2-R40</td><td>HPE-4S2-R41</td></tr></tbody></table>	Affected Model	New Version	HPE-4S2-R40	HPE-4S2-R41	
Affected Model	New Version				
HPE-4S2-R40	HPE-4S2-R41				
Affected by This Change <input type="checkbox"/> Specifications <input type="checkbox"/> Dimensions <input type="checkbox"/> Appearance <input type="checkbox"/> Package <input type="checkbox"/> Label <input type="checkbox"/> BIOS <input type="checkbox"/> Driver					
For more details please refer to the latest datasheet or visit http://www.ieiworld.com .					