

# Product Change Notification

Issue Date: May 29, 2015

**Product Name:** PPC-37xx Series

**Status:** Running change

This notice is to inform you of changes to the PPC-37xx Series.

## Reason for Change

The original power adapter (FSP060-DBAE1) was EOL.

Change power adapter from FSP060-DBAE1 to FSP060-DIBAN2.

## Description of Change

Change power adapter from FSP060-DBAE1 to FSP060-DIBAN2.

## Affected Model

Affected Model	New Version
PPC-3708A-N26/R/2G-R11	PPC-3708A-N26/R/2G-R12
PPC-3710A-N26/R/2G-R11	PPC-3710A-N26/R/2G-R12
PPC-3712A-N26/R/2G-R11	PPC-3712A-N26/R/2G-R12
PPC-3708A-N270/R/1G-R22	PPC-3708A-N270/R/1G-R23
PPC-3710A-N270/R/1G-R22	PPC-3710A-N270/R/1G-R23
PPC-3712A-N270/R/1G-R22	PPC-3712A-N270/R/1G-R23

## Affected by This Change

Specifications  Dimensions  Appearance  Package  Label  BIOS  Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,  
Evan Tsai  
Project Manager  
IEI Integration Corp.