

Product Change Notification

Issue Date: September 15, 2015

Product Name:	Status:
NANO-PV-D5252/D4252/N4552	Running change

Reason for Change

- 1. Audio IC ALC888 and scalar IC NT68667UFG already have been EOL, and IEI has run out of the stocks of ALC888.
- 2. To solve CPU overheat issue.

Description of Change

- 1. Change Audio IC from ALC888 to ALC662.
- 2. Change Scalar IC from Novatek NT68667UFG to Novatek NT68660BUFG
- 3. Change heatsink from 34000-000438-RS (H:20.58mm) to 34000-000510-RS (H:32.50mm) for NANO-PV-D5252.
- 4. Change BIOS from SA24AR12 to SA24AR15

Affected Model

Affected Model	New Version		
NANO-PV-D5252-R10	NANO-PV-D5252-R11		
NANO-PV-D4252-R10	NANO-PV-D4252-R11		
NANO-PV-N4552-R10	NANO-PV-N4552-R11		

Affected	hy This	Change
Anecteu	DV IIIIS	Change

Affected by This Change								
Specifications	Dimensions	Appearance	☐ Package	Label	■ BIOS □ Driver			
For more details please refer to the latest datasheet or visit http://www.ieiworld.com .								



NANO-PV-D5252/D4252/N4552-R10

Original Scalar IC: Novatek NT68667UFG

Original Heatsink: 34000-000438-RS

NANO-PV-D5252/D4252/N4552-R11

Change Scalar IC to Novatek NT68660BUFG

Add Heatsink for Scalar IC

New Heatsink: 34000-000510-RS (Only on

NANO-PV-D5252) (NANO-PV-D4252/N4552 keep

using original heatsink)

NANO-PV-D4252/N4552-R11



NANO-PV-D5252-R11



