

Product Change Notification

Issue Date: September 22, 2015

Product Name: AFL2-17A(B)-H61 series

Status: Running change

This notice is to inform you of changes to the AFL2-17A(B)-H61 series.

Reason for Change

(1) Phase-out of Wireless IC/module, and change wireless IC from Ralink to Atheros AR9485, Wireless driver is changed as well.

	Phase-out IC	Replacement IC
Wireless IC	Ralink RT5392L (802.11 b/g/n, 2T2R, 2.4 ~ 2.5GHz)	Atheros AR9485 (802.11 b/g/n, 1T2R, 2.4 ~ 2.5GHz)

Operating system is upgraded for new wireless driver

Affected Model	Replacement Model
AFL2-17A-H61-WES7P-R10 (for Projected Capacitive Touch)	AFL2-17A-H61-WES7P-R13 (for Projected Capacitive Touch)
AFL2-17A-H61-WES7E-R10 (for Resistive Touch)	AFL2-17A-H61-WES7E-R13 (for Resistive Touch)

(2) Phase out of Power Adapter

Specifications	Phase-out Power Adapter	Replacement Power Adapter
120W, 19V DC jack	63000-FSP120AAB-RS	63040-010120-210-RS

Affected Model

Affected Model	New Version
AFL2-17A-H61-P/R-R12	AFL2-17A-H61-P/R-R13
AFL2-17A-H61-i3/R-R12	AFL2-17A-H61-i3/R-R13
AFL2-17A-H61-i5/R-R12	AFL2-17A-H61-i5/R-R13
AFL2-17A-H61-P/PC-R12	AFL2-17A-H61-P/PC-R13
AFL2-17A-H61-i3/PC-R12	AFL2-17A-H61-i3/PC-R13
AFL2-17A-H61-i5/PC-R12	AFL2-17A-H61-i5/PC-R13
AFL2-17AB-H61-P/R-R12	AFL2-17AB-H61-P/R-R13
AFL2-17AB-H61-i3/R-R12	AFL2-17AB-H61-i3/R-R13
AFL2-17AB-H61-i5/R-R12	AFL2-17AB-H61-i5/R-R13
AFL2-17AB-H61-P/PC-R12	AFL2-17AB-H61-P/PC-R13
AFL2-17AB-H61-i3/PC-R12	AFL2-17AB-H61-i3/PC-R13
AFL2-17AB-H61-i5/PC-R12	AFL2-17AB-H61-i5/PC-R13

Affected by This Change

- Specifications
 Dimensions
 Appearance
 Package
 Certification
 Label
 BIOS
 Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

xxxxxx

Project Manager

IEI Integration Corp.