

Product Change Notification

Issue Date: September 15, 2015

Product Name: AFL2-10A-N28/R/2G-R10

Status: Running change

This notice is to inform you of changes to the AFL2-10A-N28/R/2G-R10.

Reason for Change

(1) Phase-out of Wireless IC/module, and change wireless IC from Ralink to Atheros AR9485, Wireless driver is changed as well.

	Phase-out IC	Replacement IC
Wireless IC	Ralink RT5392L (802.11 b/g/n, 2.4 ~ 2.5GHz)	Atheros AR9485 (802.11 b/g/n, 2.4 ~ 2.5GHz)

Operating system is upgraded for new wireless driver

	Affected Model	Replacement Model
Windows 7 Embedded	AFL2-W10A-CV-WES7E-R10	AFL2-W10A-CV-WES7E-R11
Windows XP Embedded	AFL2-W10A-CV-XPE-R10	AFL2-W10A-CV-XPE-R11

(2) Phase out of Power Adapter

Specifications	Phase-out Power Adapter	Replacement Power Adapter
60W, 12V DC jack	63040-010060-030-RS	63040-010060-130-RS

Affected Model

Affected Model	New Version
AFL2-10A-N28/R/2G-R10	AFL2-10A-N28/R/2G-R11

Affected by This Change

- | | | | |
|--|-------------------------------------|-------------------------------------|--|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input checked="" type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

xxxxx

Project Manager

IEI Integration Corp.