

Technical Notice

Issue Date: January 20, 2017

Product Name: IMBA-Q770-R10

Implementation Date: January 20, 2017

This notice is to inform you of changes to the IMBA-Q770 SBC series.

Reason for Change

When the motherboard pairs with CPU i7-3770, there's a small possibility that it could cause some system error.

Please contact your sales window or the technical support if this problem occurs.

Affected Model

Affected Model
IMBA-Q770-R10

Affected by This Change

- | | | | |
|--|-------------------------------------|-------------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
Jason Kao
Project Manager
IEI Integration Corp.