

Product Change Notification

Issue Date: March 15, 2016

Product Name:

AFL2-W21A-H61-P/PC-R10
 AFL2-W21A-H61-i3/PC-R10
 AFL2-W21A-H61-i5/PC-R10
 AFL2-W21AB-H61-P/PC-R10
 AFL2-W21AB-H61-i3/PC-R10
 AFL2-W21AB-H61-i5/PC-R10

Status: Running change

This notice is to inform you of changes to the AFL2-W21A series.

Reason for Change

- (1) Phase-out of Wireless IC/module, and change wireless IC from Ralink to Atheros AR9485, Wireless driver is changed as well.

	Phase-out IC	Replacement IC
Wireless IC	Ralink RT5392L (802.11 b/g/n, 2T2R, 2.4 ~ 2.5GHz)	Atheros AR9485 (802.11 b/g/n, 1T2R, 2.4 ~ 2.5GHz)

Operating system is upgraded for new wireless driver

Affected Model	Replacement Model
AFL2-W21-H61-WES7P-R10	AFL2-W21-H61-WES7P-R11
AFL2-W21-H61-XPE-R10	AFL2-W21-H61-XPE-R11

- (2) Power adapter change for IEC/EN60950 A2 version compliant with ErP certification

Item	Original Rule	New Rule
CB	IEC60950-1:2005+A1:2009	IEC60950-1:2005+A1:2009+A2:2013
TUV/N/D/S/F	EN60950-1:2006+A11:2009 +A1:2010+A12:2011	EN60950-1:2006+A11:2009+A1:2010+A 12:2011+A2:2013

Specifications	Phase-out Power Adapter	Replacement Power Adapter
120W, 19V DC jack	63000-FSP120AAB-RS	63040-010120-210-RS

Affected Model

Affected Model	New Version
AFL2-W21A-H61-P/PC-R10	AFL2-W21A-H61-P/PC-R11
AFL2-W21A-H61-i3/PC-R10	AFL2-W21A-H61-i3/PC-R11
AFL2-W21A-H61-i5/PC-R10	AFL2-W21A-H61-i5/PC-R11
AFL2-W21AB-H61-P/PC-R10	AFL2-W21AB-H61-P/PC-R11
AFL2-W21AB-H61-i3/PC-R10	AFL2-W21AB-H61-i3/PC-R11
AFL2-W21AB-H61-i5/PC-R10	AFL2-W21AB-H61-i5/PC-R11

Affected by This Change

- ☒ Specifications
 ☐ Dimensions
 ☐ Appearance
 ☐ Package
☐ Certification
 ☐ Label
 ☐ BIOS
 ☒ Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
 Marlene Lo
 Project Manager
 IEI Integration Corp.