

# Product Change Notification

Issue Date: June 7, 2016

**Product Name: AFL-xxi-HM55 series**

**Status: Running change**

This notice is to inform you of changes to the AFL-xxi-HM55 series.

## Reason for Change

- Phase-out of TFT LCD

LCD Size	Affected P/N	Replacement P/N
15"	IEI P/N :23000-000249-RS (AUO, G150XG01 V3)	IEI P/N :23000-000331-RS (AUO, G150XTN06.0)
17"	IEI P/N :23000-000203-RS (AUO, G170EG01 V0)	IEI P/N: 23000-000263-RS (AUO, G170EG01 V1)

## Affected Model

Affected Model	Replacement Model
AFL-17i-HM55-P45/R/1G-R13	AFL-17i-HM55-P45/R/1G-R20
AFL-17i-HM55i3-35/R/2G-R13	AFL-17i-HM55i3-35/R/2G-R20
AFL-17i-HM55i5-52/R/2G-R13	AFL-17i-HM55i5-52/R/2G-R20
AFL-17i-HM55i7-62/R/2G-R13	AFL-17i-HM55i7-62/R/2G-R20
AFL-15i-HM55-P45/R/1G-R21	AFL-15i-HM55-P45/R/1G-R30
AFL-15i-HM55i3-35/R/2G-R21	AFL-15i-HM55i3-35/R/2G-R30
AFL-15i-HM55i5-52/R/2G-R21	AFL-15i-HM55i5-52/R/2G-R30
AFL-15i-HM55i7-62/R/2G-R21	AFL-15i-HM55i7-62/R/2G-R30

## Affected by This Change

- Specifications     
  Dimensions     
  Appearance     
  Package  
 Certification     
  Label     
  BIOS     
  Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Marlene Lo

Project Manager

IEI Integration Corp.