

Technical Notice

Issue Date: March 31, 2017

Product Name: DM-F19A/R-R10

Implementation Date: March 31, 2017



This notice is to inform you of changes to the DM-F19A/R-R10.

Reason for Change

To solve the issue that the original RS-232 touch cable (optional, DM-F-COMKIT-R10) is too short to use with the DM-F19A/R-R10 monitor.

Description of Change

Change the optional RS-232 touch cable for DM-F19A/R-R10 from DM-F-COMKIT-R10 (200 mm) to DM-F-COMKIT01-R10 (300 mm).

DM-F-COMKIT-R10 (Original)	DM-F-COMKIT01-R10 (Replacement)
	

Affected Model

Affected Model
DM-F19A/R-R10

Affected by This Change

g Specifications	c Dimensions	c Appearance	c Package
c Certification	c Label	c BIOS	c Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
Henry
Project Manager
IEI Integration Corp.*