

Technical Notice

Issue Date: Oct.1, 2018

Product Name: TANK-870AI	Implementation Date: Oct. 1, 2018					
This notice is to inform you of changes to the TANK-870Al series.						
Reason for Change Solve WIFI module (AW-CB161H) error code and failed to link website issue in Ubuntu OS.						
□ □ ubuntu@ubuntu: □ [51.015981] pcieport 0000:00:1d.0: AER: Corrected error received: id=00e8 [51.015990] pcieport 0000:00:1d.0: PCIe Bus Error: severity=Corrected, type=P hysical Layer, id=00e8(Receiver ID) [51.015997] pcieport 0000:00:1d.0: device [8086:a119] error status/mask=000 [51.015999] pcieport 0000:00:1d.0: [0] Receiver Error [51.016012] pcieport 0000:00:1d.0: AER: Corrected error received: id=00e8 [51.016028] pcieport 0000:00:1d.0: PCIe Bus Error: severity=Corrected, type=P hysical Layer, id=00e8(Receiver ID)						
Description of Change						
Change Ubuntu 16.04 image from VC12ER11 (5424D-100111-RS) to VC12ER12 (5424D-100212-RS).						
Change BIOS version from V2RMAR13 (5300N-0R013	30-00-RS) to V2RMAR14 (5300N-0R0140-00-RS).					
Affected Model						
Affected Model						
TANK-870AI-i5/8G/2A-R10						
TANK-870AI-i5KBL/8G/2A-R10						
TANK-870AI-i7/8G/2A-R10						
TANK-870AI-i7KBL/16G/2A-R10						
Affected by This Change						
☐ Specifications ☐ Dimensions	Appearance Package					
☐ Certification ☐ Label	■ BIOS ■ Driver					
For more details please refer to the latest datasheet or visit http://www.ieiworld.com .						
Best Regards,						
Wilson Wu						



Project Manager IEI Integration Corp.			