

Product Change Notification

Issue Date: Aug. 24 2018

Product Name: DRPC-130-AL	Status: Running change
----------------------------------	-------------------------------



This notice is to inform you of changes to the DRPC-130-AL series.

Reason for Change

1. Add three holes on mechanism to support Din Rail Hook

Description of Change

1. Add three holes on mechanism to support Din Rail Hook
2. Remove Wall Mount Bracket (41120-0507C2-00-RS)
3. Add Din Rail Hook (42011-0025E4-00-RS)

DRPC-130-AL R10 Series	DRPC-130-AL R11 Series
	

Affected Model

Affected Model	New Version
DRPC-130-AL-E1-R10	DRPC-130-AL-E1-R11
DRPC-130-AL-E1/4GB-R10	DRPC-130-AL-E1/4GB-R11

Affected by This Change

- | | | | |
|--|-------------------------------------|--|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
Wilson Wu
Project Manager
IEI Integration Corp.