

Product Change Notification

Issue Date: Jan. 20, 2022

Product Name: MUSTANG-M2BM-MX2

Status: Implement on next production

This notice is to inform you of changes to the MUSTANG-M2BM-MX2.

Reason for Change

1. PCIe to USB IC - FL1100 shortage
2. ID Switch change to 2bit.

Description of Change

- Change PCIe to USB IC from 248BL-000003-RS to 248M1-000001-RS (EJ188)
- Change ID Switch from 31301-000149-RS to 31301-000179-HF

Affected Model

Affected Model	New Version
MUSTANG-M2BM-MX2-NC-R10	MUSTANG-M2BM-MX2-NC-R20
MUSTANG-M2BM-MX2-R10	MUSTANG-M2BM-MX2-R20

Affected by This Change

- Specifications Dimensions Appearance Package
 Certification Label BIOS Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
Morton Lee
Project Manager
IEI Integration Corp.*