

# Product Change Notification

Issue Date: Aug 22, 2019

**Product Name:** Mustang-V100-MX8

**Status:** Running change

This notice is to inform you of changes to the Mustang-V100-MX8 product.

## Reason for Change

Mustang-V100-MX8-R10 will be EOL.

Enhance compatibility for some host systems' PCIe slot with no SMBUS signal.

## Description of Change

Change VPU reset mechanism from MCU to USB.

## Affected Model

| Affected Model       | New Version          |
|----------------------|----------------------|
| Mustang-V100-MX8-R10 | Mustang-V100-MX8-R11 |

## Affected by This Change

- Specifications       Dimensions       Appearance       Package  
 Certification       Label       BIOS       Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,  
Malcolm  
Project Manager  
IEI Integration Corp.*