

Product Change Notification

Issue Date: Nov 19, 2020

Product Name: PUZZLE-IN001series

Status: Running change

This notice is to inform you of implement on next production to the PUZZLE-IN001 series.

Reason for Change

1. Revised safety certification in compliance with EN 62368-1
2. Change LCM mylar without IEI and PUZZLE logo
3. Add Carton package
4. PUZZLE-IN001-R-R10 sku without Heatsink.

Description of Change

1. Change adapter 63050-010300-020-RS and 63050-010320-000-RS to 63050-010300-220-RS and 63050-010320-100-RS. Update safety certification from EN 60950 to EN 62368-1.
2. Change LCM mylar without IEI/ PUZZLE logo.
3. Add one outside carton package
4. PUZZLE-IN001-R-R11 barebone sku without heatsink, A CPU heatsink must be purchased separately.

Affected Model

Affected Model	New Version
PUZZLE-IN001-R-R10	PUZZLE-IN001-R-R11
PUZZLE-IN001-XE/R-R10	PUZZLE-IN001-XE/R-R11
PUZZLE-IN001-i3T/R-R10	PUZZLE-IN001-i3T/R-R11
PUZZLE-IN001-XE/16G/R-R10	PUZZLE-IN001-XE/16G/R-R11
PUZZLE-IN001-i3T/16G/R-R10	PUZZLE-IN001-i3T/16G/R-R11

Affected by This Change

- | | | | |
|---|---|--|---|
| <input type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input checked="" type="checkbox"/> Package |
| <input checked="" type="checkbox"/> Certification | <input checked="" type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Fini Lin

Project Manager

IEI Integration Corp.

