

Product Change Notification

Issue Date: February 5, 2021

Product Name: PPC-F15/17A-H81 Series

Status: Running change

This notice is to inform you of changes to the PPC-F15/17A-H81 series.

Reason for Change

1. The safety standard IEC 60950 is officially withdrawn and replaced by IEC 62368-1.
2. Realtek announced the End of Life (EOL) of ALC662 Series High Definition Audio Codec IC due to the shortage of wafer and promptly FAB capacity issue.

Description of Change

1. Change the PSU from ACE-A622B to ACE-A622C for IEC 62368-1 compliance.
2. Change the audio IC from ALC662 to ALC888S; add ALC888S audio decode support in BIOS.

Affected Model

Affected Model	New Version
PPC-F15AA-H81i-i5/4G/PC-R22	PPC-F15AA-H81i-i5/4G/PC-R23
PPC-F15AA-H81i-i5/4G/R-R22	PPC-F15AA-H81i-i5/4G/R-R23
PPC-F15AA-H81i-P/4G/PC-R22	PPC-F15AA-H81i-P/4G/PC-R23
PPC-F15AA-H81i-P/4G/R-R22	PPC-F15AA-H81i-P/4G/R-R23
PPC-F17AA-H81i-i5/4G/PC-R13	PPC-F17AA-H81i-i5/4G/PC-R14
PPC-F17AA-H81i-i5/4G/R-R13	PPC-F17AA-H81i-i5/4G/R-R14
PPC-F17AA-H81i-P/4G/PC-R13	PPC-F17AA-H81i-P/4G/PC-R14
PPC-F17AA-H81i-P/4G/R-R13	PPC-F17AA-H81i-P/4G/R-R14

Affected by This Change

- Specifications Dimensions Appearance Package
 Certification Label BIOS Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
Henry Kao
Project Manager
IEI Integration Corp.