

# Technical Notice

**Issue Date: July 23, 2024**

**Product Name:** WAFER-EHL-x6000 Series

**Implementation Date:** July 23, 2024

**Implementation Status:** Running change

This notice is to inform you of changes to the WAFER-EHL-x6000 SBC series.

## Reason for Change

Intel® Ethernet Controller I225 shortage issues.

## Description of Change

Change LAN IC from Intel® Ethernet Controller I225-IT to Intel® Ethernet Controller I226-IT.

## Affected Model

Affected Model
WAFER-EHL-x6211EWC-R10
WAFER-EHL-x6413EWC-R10
WAFER-EHL-x6425EWC-R10

## Affected by This Change

- |  |                                     |  |                                  |
|--|-------------------------------------|--|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification             | <input type="checkbox"/> Label      | <input checked="" type="checkbox"/> BIOS       | <input type="checkbox"/> Driver  |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,*  
*Maixin Li*  
*Project Manager*  
*IEI Integration Corp.*