

# Product Change Notification

**Issue Date:** August 19, 2024

**Product Name:** IMBA-Q470、PCIE-Q470

**Status:** Running change

This notice is to inform you of changes to the:

1. IMBA-Q470-R10
2. PCIE-Q470-R10

### Reason for Change

1. Intel® Ethernet Controller I225 shortage issues.

### Description of Change

1. Change LAN IC from Intel® Ethernet Controller I225-LM / I225-V to Intel® Ethernet Controller I226-LM / I226-V.

### Affected Model

Affected Model	New Version
IMBA-Q470-R10	IMBA-Q470-R11
PCIE-Q470-R10	PCIE-Q470-R11

### Affected by This Change

- Specifications       Dimensions       Appearance       Package  
 Certification       Label       BIOS       Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,*  
*Maixin Li*  
*Product Manager*  
*IEI Integration Corp.*