

Product Change Notification

Issue Date: August 22, 2024

Product Name: Motherboard series

Status: Running change

This notice is to inform you of changes to the :

1. IMB-Q470-R10
2. IMBA-H420-R10
3. IMB-H420-R10
4. IMBA-Q471-R10
5. IMBA-R680-R10
6. KINO-ADL-H610-R10
7. IMBA-ADL-H610-R10

Reason for Change

1. Intel® Ethernet Controller I225 shortage issues.

Description of Change

1. Change LAN IC from Intel® Ethernet Controller I225-LM / I225-V to Intel® Ethernet Controller I226-LM / I226-V.

Affected Model

Affected Model	New Version
IMB-Q470-R10	IMB-Q470-R11
IMBA-H420-R10	IMBA-H420-R11
IMB-H420-R10	IMB-H420-R11
IMBA-Q471-R10	IMBA-Q471-R11
IMBA-R680-R10	IMBA-R680-R11
KINO-ADL-H610-R10	KINO-ADL-H610-R11
IMBA-ADL-H610-R10	IMBA-ADL-H610-R11

Affected by This Change

- | | | | |
|--|-------------------------------------|--|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input checked="" type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
Maixin Li
Product Manager
IEI Integration Corp.*