

## **iEi Products Product Change Notice**

**Phase-out Model:** IMB-9454G-R20, WSB-Q354-R10, WSB-9452-R20 WSB-9452S-R20 and WSB-9452SDVI-R20

Status: Running Change

Dear Partners,

iEi appreciate you daily support on IPC business.

We would like to notify you for the phase-out models will be implemented into revision R40. It is mainly due to the long lead-time issue of Broadcom Ethernet chipset BCM5787M on above models. Therefore, we have to modify them to implement Realtek Ethernet chipset RTL8111E with regular lead-time as new revision R40 models of IMB-9454G-R40, WSB-Q354-R40, WSB-9452-R40 WSB-9452S-R40 and WSB-9452SDVI-R40. This method makes iEi products that can delivery to you on time and there is no any impact to the functionality of Ethernet usage. Other change is that change PLCC BIOS to SPI BIOS EEPROM package except WSB-Q354-R40.

We would like to share the information with partners as early as possible. However, please do not hesitate to contact us while you have any further comments.

Yours Faithfully, Duke Hsieh Product Manager IEI Technology corp.