

Issued date: 2012/5/22

Product Change Notification

Status: Running Change

Dear valued partner,

We would like to notify you the phase-out notice for the Revision 11 of AFL-xxi-HM55 series by May 22, 2012. Please refer to attachment A for detailed list of discontinued products and information on the phase out models.

Phase out reasons:

- Phase out of audio codec Realtek ALC888 and change to Realtek ALC892
- Add EEPROM to MCU IC to increase product reliability

Attachment A:

Phase Out Model	Replacement Model
AFL-15i-HM55-P45/R/1G-R11	AFL-15i-HM55-P45/R/1G-R12
AFL-15i-HM55i3-35/R/2G-R11	AFL-15i-HM55i3-35/R/2G-R12
AFL-15i-HM55i5-52/R/2G-R11	AFL-15i-HM55i5-52/R/2G-R12
AFL-15i-HM55i7-62/R//2G-R11	AFL-15i-HM55i7-62/R//2G-R12
AFL-15iE-HM55-P45/R/1G-R11	AFL-15iE-HM55-P45/R/1G-R12
AFL-15iE-HM55i3-35/R/2G-R11	AFL-15iE-HM55i3-35/R/2G-R12
AFL-15iE-HM55i5-52/R/2G-R11	AFL-15iE-HM55i5-52/R/2G-R12
AFL-15iE-HM55i7-62/R/2G-R11	AFL-15iE-HM55i7-62/R/2G-R12
AFLSD-15-HM55-2G-XPE-R10	AFLSD-15-HM55-2G-XPE-R12
AFL-17i-HM55-P45/R/1G-R11	AFL-17i-HM55-P45/R/1G-R12
AFL-17i-HM55i3-35/R/2G-R11	AFL-17i-HM55i3-35/R/2G-R12
AFL-17i-HM55i5-52/R/2G-R11	AFL-17i-HM55i5-52/R/2G-R12
AFL-17i-HM55i7-62/R//2G-R11	AFL-17i-HM55i7-62/R//2G-R12
AFLSD-17-HM55-2G-XPE-R10	AFLSD-17-HM55-2G-XPE-R12
AFL-19i-HM55-P45/R/1G-R11	AFL-19i-HM55-P45/R/1G-R12
AFL-19i-HM55i3-35/R/2G-R11	AFL-19i-HM55i3-35/R/2G-R12
AFL-19i-HM55i5-52/R/2G-R11	AFL-19i-HM55i5-52/R/2G-R12
AFL-19i-HM55i7-62/R//2G-R11	AFL-19i-HM55i7-62/R//2G-R12
AFLSD-19-HM55-2G-XPE-R10	AFLSD-19-HM55-2G-XPE-R12

Please do not hesitate to contact us while you have any further comments.

Yours Faithfully,

Marlene Lo

Product Manager

IEI Technology corp.