


Product Change Notification

Issue Date: November 5, 2015

Product Name: NOVA-PV-D5251	Status: Running change								
Reason for Change Scalar IC NT68667UFG already have been EOL, and IEI has run out of the stocks of NT68667UFG.									
Description of Change 1. Change Scalar IC from Novatek NT68667UFG to Novatek NT68660BUFG									
Affected Model									
<table border="1"><thead><tr><th>Affected Model</th><th>New Version</th></tr></thead><tbody><tr><td>NOVA-PV-D5251-G2L2-R11</td><td>NOVA-PV-D5251-G2L2-R12</td></tr><tr><td>NOVA-PV-D5251-G4-R11</td><td>NOVA-PV-D5251-G4-R12</td></tr><tr><td>NOVA-PV-D4251-G2L2-R11</td><td></td></tr></tbody></table>	Affected Model	New Version	NOVA-PV-D5251-G2L2-R11	NOVA-PV-D5251-G2L2-R12	NOVA-PV-D5251-G4-R11	NOVA-PV-D5251-G4-R12	NOVA-PV-D4251-G2L2-R11		
Affected Model	New Version								
NOVA-PV-D5251-G2L2-R11	NOVA-PV-D5251-G2L2-R12								
NOVA-PV-D5251-G4-R11	NOVA-PV-D5251-G4-R12								
NOVA-PV-D4251-G2L2-R11									
Affected by This Change <input checked="" type="checkbox"/> Specifications <input type="checkbox"/> Dimensions <input checked="" type="checkbox"/> Appearance <input type="checkbox"/> Package <input checked="" type="checkbox"/> Label <input type="checkbox"/> BIOS <input type="checkbox"/> Driver									
For more details please refer to the latest datasheet or visit http://www.ieiworld.com .									

NOVA-PV-D5252/D4252/N4552-R10

Original Scalar IC: Novatek NT68667UFG



NOVA-PV-D5252/D4252/N4552-R11

Change Scalar IC to Novatek NT68660BUFG
Add Heatsink for Scalar IC

