

Product Change Notification

Issue Date: March 29, 2016

Product Name: AFL3-W15A-BT series

Status: Running change

This notice is to inform you of changes to the AFL3-W15A-BT series.


Reason for Change

- Phase-out of PCAP touch controller IC

Affected P/N	Replacement P/N
75200-02015607MX-RS (touch controller : EETI EXC7200)	75200-02015608BS-RS (touch controller :EETI EXC3188)

- USB board upgrade to USB hub board

Affected P/N	Replacement P/N
134A048-00-102-RS (Bypass two USB 2.0 to two USB2.0)	134F346-00-100-RS (One USB 2.0 convert to two USB 2.0)



Affected Model

Affected Model	Replacement Model
AFL3-W15A-BT-J1/PC/2G-R10	AFL3-W15A-BT-J1/PC/2G-R11
AFL3-W15A-BT-J1/R/2G-R10	AFL3-W15A-BT-J1/R/2G-R11

Affected by This Change

- | | | | |
|--|-------------------------------------|-------------------------------------|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
Marlene Lo
Project Manager
IEI Integration Corp.*