

Issued date: 2014/08/12



Product Change Notice

Phase-out Model: HPE-5S1-R50 & HPE-3S1-R40

Phase-in Model: HPE-5S1-R51 & HPE-3S1-R41

Status: Running change

Dear Customers,

We would like to inform you the update of the HPE-5S1 & HPE-3S1 backplane. In this update, we solved the issue regarding the 3.3V power problem which was caused when the motherboard was set to AT power mode. The latest available versions of this models are: HPE-5S1-R51 & HPE-3S1-R41.

IEI appreciates your daily support and business. Please do not hesitate to contact us if you have any further questions or comments.

Yours faithfully

John Lin

Product Manager