

Issued date: 2014/04/28

# Products Change Notice

## Affective Models:

MODAT-100-WB65-En  
 MODAT-100-WB65-Sc  
 MODAT-100-WB65-Tc  
 MODAT-100-RFID-WB65-En  
 MODAT-100-2D-WB65-En  
 MODAT-328-WB65-En-R11  
 MODAT-328-WB65-Sc-R11  
 MODAT-328-WB65-Tc-R11  
 MODAT-335-WB65-En-E-R11  
 MODAT-335-GPRS-WB65-En-E-R11  
 MODAT-335-1D-WB65-En-R11

Dear valued partner,

We would like to notify you for the phase-out model will be replaced. Due to 3M camera module EOL, iEi Integration changed the camera module from 3M to 5M.

Affected Model	Changes	Affected Module
MODAT-100-WB65-En	MODAT-100-WB65-En-E-R11	Change 3M camera to 5M camera
MODAT-100-WB65-Sc	MODAT-100-WB65-Sc-E-R11	
MODAT-100-WB65-Tc	MODAT-100-WB65-Tc-E-R11	
MODAT-100-RFID-WB65-En	MODAT-100-RFID-WB65-En-E-R11	
MODAT-100-2D-WB65-En	MODAT-100-2D-WB65-En-E-R11	
MODAT-328-WB65-En-R11	MODAT-328-WB65-En-R12	
MODAT-328-WB65-Sc-R11	MODAT-328-WB65-Sc-R12	
MODAT-328-WB65-Tc-R11	MODAT-328-WB65-Tc-R12	
MODAT-335-WB65-En-E-R11	MODAT-335-WB65-En-E-R12	
MODAT-335-GPRS-WB65-En-E-R11	MODAT-335-GPRS-WB65-En-E-R12	
MODAT-335-1D-WB65-En-R11	MODAT-335-1D-WB65-En-R12	

Please do not hesitate to contact us while you have any further comments.

Yours Faithfully,

**Oliver Yu**

**Product Manager**

**IEI Integration Technology corp.**