

Technical Notice

Issue Date: December 2, 2014

Product Name: WAFER-PV-D5252 SBC WAFER-PV-N4552 SBC

Status: Running change

Dear Customers,

This notice is to inform you that the audio controller of the WAFER-PV-D5252/N4552 series has been changed from ALC888 to ALC662 due to the EOL of ALC888. Although the motherboard version remains the same as before (R10), you can still check the serial number to know which board is installed with the new ALC888 audio controller. Please refer to the following tables for in-depth information.

We apologize for not informing you earlier and not upgrading the version in a timely manner. We will soon issue a Product Change Notice to announce the version change of the WAFER-PV-D5252/N4552 series. Again many apologies for any inconvenience this may have caused, and thanks for your daily support on IPC business.

Reason for Change

ALC888 has already been EOL, and IEI has run out of the stocks of ALC888.

Description of Change

Changed the audio controller from ALC888 to ALC662.

Changed the BIOS from E338AR24 to E338AR25

Affected Model

WAFER-PV-D5252-R10	SN < SC14730101	SN ≧ SC14730101	
Serial number (SN)	311 < 3014730101		
Audio IC	ALC888	ALC662	

WAFER-PV-N4552-R10 Serial number (SN)	SN < SC14800627	SN ≧ SC14800627
Audio IC	ALC888	ALC662

Affected by This Change

Specifications	Dimensions	Appearance	🗌 Package	Label	BIOS	Driver	
For more details please refer to the latest datasheet or visit http://www.ieiworld.com.							