

Technical Notice

Issue Date: January 18, 2016

Product Name: NANO-QM871-i1/ECN-380-QM87i

Implementation Date: January 18, 2016

This notice is to inform you of changes to the NANO-QM871-i1 & ECN-380-QM87i series.

Reason for Change

Improve mSATA capability.

Description of Change

Remove 0 Ω resistors on R556, R557 and R559 to improve mSATA capability.

Affected Model

Affected Model
NANO-QM871-i1-i7-R10
NANO-QM871-i1-i5-R10
NANO-QM871-i1-i5E-R10
NANO-QM871-i1-i3-R10
NANO-QM871-i1-i3E-R10
NANO-QM871-i1-C-R10
NANO-QM871-i1-CE-R10
ECN-380-QM87i-i5/4G-R10
ECN-380-QM87i-i5-R10
ECN-380-QM87i-i5/WD/4G-R10
ECN-380-QM87i-i5/WD-R10
ECN-380-QM87i-C/WD/4G-R10
ECN-380-QM87i-C/4G-R10
ECN-380-QM87i-C/WD-R10
ECN-380-QM87i-C-R10

Affected by This Change

- | | | | |
|---|-------------------------------------|-------------------------------------|----------------------------------|
| <input type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
Yiyu Huang
Project Manager
IEI Integration Corp.*