

Product Change Notification

Issue Date: May 26, 2015

Product Name: AFL-15AE-N270/R/1G-R22	Status: Running change
--	-------------------------------

This notice is to inform you of changes to the AFL-15AE-N270 series.

Reason for Change:

- (1) Phase-out of Wireless IC/module, and change wireless IC from Ralink RT5392L to Atheros AR9485, Wireless driver is changed as well.

Item	Phase-out Wireless Module	Replacement Wireless Module
IEI P/N	27302-000001-RS	27303-000006-RS
Wireless IC	Ralink RT3090 (802.11 b/g/n, 2.4 ~ 2.5GHz)	Atheros AR9485 (802.11 b/g/n, 2.4 ~ 2.5GHz)

(2) Phase out of Power Adapter

Item	Phase-out Power Adapter	Replacement Power Adapter
IEI P/N	63040-010060-050-RS	63040-010060-110-RS
Manufacturer's P/N	FSP; FSP060-DBAE1	FSP; FSP060-DIBAN2
Specification	Vin:90~264VAC;60W;Vout:12VDC ;4Pin/lock	Vin:90~264VAC;60W;Vout:12VDC ;4Pin/lock

Affected Model

Affected Model	Replacement Model
AFL-15AE-N270/R/1G-R22	AFL-15AE-N270/R/1G-R23

Affected by This Change

Specifications
 Dimensions
 Appearance
 Package
 Label
 BIOS
 Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Marlene Lo

Project Manager

IEI Integration Corp.