

Product Change Notification

Issue Date: May 29, 2015

Product Name: PPC-37xx Series

Status: Running change

This notice is to inform you of changes to the PPC-37xx Series.

Reason for Change

The original power adapter (FSP060-DBAE1) was EOL.

Change power adapter from FSP060-DBAE1 to FSP060-DIBAN2.

Description of Change

Change power adapter from FSP060-DBAE1 to FSP060-DIBAN2.

Affected Model

Affected Model	New Version
PPC-3708A-N26/R/2G-R12	PPC-3708A-N26/R/2G-R12
PPC-3710A-N26/R/2G-R12	PPC-3710A-N26/R/2G-R12
PPC-3712A-N26/R/2G-R12	PPC-3712A-N26/R/2G-R12
PPC-3708A-N270/R/1G-R23	PPC-3708A-N270/R/1G-R23
PPC-3710A-N270/R/1G-R23	PPC-3710A-N270/R/1G-R23
PPC-3712A-N270/R/1G-R23	PPC-3712A-N270/R/1G-R23

Affected by This Change

Specifications Dimensions Appearance Package Label BIOS Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
Evan Tsai
Project Manager
IEI Integration Corp.