

Product Change Notification

Issue Date: Nov,10, 2015

Product Name: IMBA-C2260-i2-R11

Status: Implement on next production

Reason for Change

Change PCIe x 1 connector to PCIe x 4 connector for higher speed bus.

Description of Change


Replace PCIe x 1 slot to PCIe x 4 slot

Affected by This Change

Specifications Dimensions Appearance Package Label BIOS Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

IMBA-C2260-i2-R10:



IMBA-C2260-i2-R11:

(Replace PCIe x 1 connector to PCIe x 4)

