

Product Change Notification

Issue Date: October 27, 2015

Product Name: AFL2-W10A-N28/R/2G-R10 Status: Running change

This notice is to inform you of changes to the AFL2-W10A-N28 series.

Reason for Change

(1) Phase-out of Wireless IC/module, and change wireless IC from Ralink to Atheros AR9485, Wireless driver is changed as well.

	Phase-out IC	Replacement IC	
Wireless IC	Ralink RT5392L	Atheros AR9485	
	(802.11 b/g/n, 2.4 ~ 2.5GHz)	(802.11 b/g/n, 2.4 ~ 2.5GHz)	

Operating system is upgraded for new wireless driver

	Affected Model	Replacement Model	
Windows 7 Embedded	AFL2-W10A-CV-WES7E-R10	AFL2-W10A-CV-WES7E-R11	
Windows XP Embedded AFL2-W10A-CV-XPE-R10 AFL2-W10A-CV-XPE-R		AFL2-W10A-CV-XPE-R11	

(2) Phase out of Power Adapter

Specifications	Phase-out Power Adapter	Replacement Power Adapter
60W,12V DC jack	63040-010060-030-RS	63040-010060-130-RS

Affected Model

Affected Model	New Version
AFL2-W10A-N28/R/2G-R10	AFL2-W10A-N28/R/2G-R11
AFL2-W10A-N28/PC/2G-R10	AFL2-W10A-N28/PC/2G-R11



Affected by This Change						
Specifications	☐ Dimensions	Appearance	☐ Package			
☐ Certification	Label	BIOS	Driver			
For more details please refer to the latest datasheet or visit http://www.ieiworld.com .						
Best Regards,						
Marlene Lo						
Project Manager						
IEI Integration Corp.						