

# Product Change Notification

Issue Date: Mar 23, 2016

<b>Product Name:</b> UPC-V315-QM77-R10 Series	<b>Status:</b> Running change
---	-------------------------------

This notice is to inform you of changes to the UPC-V315-QM77-R10 Series.

## Reason for Change

- (1) Change power adapter
- (2) Upgrade auto dimming IC
- (3) Change LCD panel
- (4) Add camera substitution

## Description of Change

- (1) Change power adapter from 63040-010090-050-RS to 63040-010090-101-RS
- (2) Change auto dimming board from 13ZSB90-00-200-RS to 13ZF303-00-300-RS
- (3) Change LCD panel from 23000-000249-RS to 23000-000331-RS
- (4) Add camera substitution: 7I002-AG5020B17S13T-RS

## Affected Model

Affected Model	New Version
UPC-V315-QM77-C/R/2G-R10	UPC-V315-QM77-C/R/2G-R20
UPC-V315-QM77-i3/R/2G-R10	UPC-V315-QM77-i3/R/2G-R20
UPC-V315-QM77-i7/R/2G-R10	UPC-V315-QM77-i7/R/2G-R20

## Affected by This Change

☒ Specifications ☐ Dimensions ☐ Appearance ☐ Package ☐ Label ☐ BIOS ☐ Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,  
Evan Tsai  
Project Manager  
IEI Integration Corp.