

Product Change Notification

Issue Date: October 4, 2016

Product Name:

AFL2-12A-HM65/PC-R14

AFL2-12A-HM65/R-R14

Status: Running change

This notice is to inform you of changes to the AFL2-12A-HM65 series.

Reason for Change

- Phase-out of Audio Codec and Amplifier IC, and re-layout the motherboard to upgrade the function

	Affected P/N	Replacement P/N
Motherboard	IEI P/N : 00ESA48-00-111-RS	IEI P/N : 00ESA48-00-112-RS
Audio Codec	IEI P/N : 24757-000011-RS Manufacturer P/N: ALC888-GR	IEI P/N : 24757-000020-RS Manufacturer P/N: ALC892-GR
Amplifier IC	IEI P/N :24B54-000001-RS Manufacturer P/N: TDA1517P/N3	24774-000011-RS Manufacturer P/N: TI;TPA1517DWPRG4

Affected Model

Affected Model	Replacement Model
AFL2-12A-HM65/PC-R14	AFL2-12A-HM65/PC-R15
AFL2-12A-HM65/R-R14	AFL2-12A-HM65/R-R15

Affected by This Change

- ☒ Specifications
 ☐ Dimensions
 ☐ Appearance
 ☐ Package
☐ Certification
 ☐ Label
 ☐ BIOS
 ☒ Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,

Marlene Lo

Project Manager

IEI Integration Corp.