

Product Change Notification

Issue Date: March 22, 2017

Product Name: EBC-3220 chassis

Status: Running change

This notice is to inform you of changes to the EBC-3220 chassis.

Reason for Change


Change the chassis assembly method for product compatible enhancement

Description of Change

Change product from EBC-3220-R10 to EBC-3220-R11.


1. Chassis assembly method
2. Power switch module to reduce the mechanical interference with motherboard I/O
3. The lock method of HDD bay

Original:



Detail please refer to QIG V1.00 (PN:51000-023903-RS)

NEW:



Detail please refer to QIG V1.10 (PN: 51000-024253-RS)

Affected Model

Affected Model	New Version
EBC-3220-R10	EBC-3220-R11

Affected by This Change

- Specifications Dimensions Appearance Package
 Certification Label BIOS Driver

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
 Elinor Chuang
 Product Manager
 IEI Integration Corp.*