



Note:

1. Material: SECC, Thickness: 1.0mm
2. Surface treatment: 外部面 Painting PMS 877C(细织纹)
3. Break all sharp edges & corners free from burrs. finished part must be free of all deburring shavings and particles.
4. Nut & Standoff must be precisely firmed.
5. Unspecified radius is R=2mm.
6. Unspecified internal radius is R=1.0mm.

7. check point: (A) (E)

