

Technical Notice

Issue Date: September 13, 2023

Product Name: Related IEI Standard SBC Products	Implementation Date: September 13, 2023
---	--

This notice is to inform you of changes to the:

Reason for Change

Avoid loosening of the M.2 plastic clips

Description of Change

change M.2 plastic clips to stud screws

Affected Model

Affected Model
IMBA-ADL-Q670-R10
IMBA-ADL-H610-R10
IMBA-Q470-R10
IMBA-Q471-R10
IMB-ADL-H610-R10
KINO-TGL-U-C-R10
KINO-TGL-U-CE-R10
KINO-TGL-U-i3-R10
KINO-TGL-U-i5-R10
KINO-TGL-U-i7-R10
NANO-ADL-P-CC-R10
NANO-ADL-P-i3C-R10
NANO-ADL-P-i5C-R10
NANO-ADL-P-i7C-R10
WAFER-EHL-J6412C-R10

Affected by This Change

- | | | | |
|--|-------------------------------------|--|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Technical Notice

Issue Date: July 23, 2024

Product Name: IEI standard products

Implementation Date: July 23, 2024

Implementation Status: Running change

This notice is to inform you of changes to the IMBA-R680 / IMBA-ADL-Q670 / IMB-ADL-Q670 / IMBA-ADL-H610 / IMB-ADL-H610 / KINO-ADL-H610 / KINO-ADLPS / IMBA-Q470 / IMBA-Q471 / IMB-Q470 / IMBA-H420 / IMB-H420 / KINO-DH420 / PCIE-Q470 / HPCIE-Q470 series.

Reason for Change

Intel® Ethernet Controller I225 shortage issues.

Description of Change

Change LAN IC from Intel® Ethernet Controller I225-LM/I225-V to Intel® Ethernet Controller I226-LM/I226-V.

Affected Model

Affected Model
IMBA-R680-R10
IMBA-ADL-Q670-R10
IMB-ADL-Q670-R10
IMBA-ADL-H610-R10
IMB-ADL-H610-R10
KINO-ADL-H610-R10
IMBA-Q470-R10
IMBA-Q471-R10
IMB-Q470-R10
IMBA-H420-R10
IMB-H420-R10
KINO-DH420-R10
KINO-ADLPS-C-R10
KINO-ADLPS-i3-R10
KINO-ADLPS-i5-R10
KINO-ADLPS-i7-R10

PCIE-Q470-R10

HPCI-E-Q470-R10

Affected by This Change

- | | | | |
|--|-------------------------------------|--|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input checked="" type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
Maoxin Li
Project Manager
IEI Integration Corp.