

Technical Notice

Issue Date: September 13, 2023

Product Name:

Related IEI Standard SBC Products

Implementation Date: September 13, 2023

This notice is to inform you of changes to the:

Reason for Change

Avoid loosening of the M.2 plastic clips

Description of Change

change M.2 plastic clips to stud screws

Affected Model

Affected Model
IMBA-ADL-Q670-R10
IMBA-ADL-H610-R10
IMBA-Q470-R10
IMBA-Q471-R10
IMB-ADL-H610-R10
KINO-TGL-U-C-R10
KINO-TGL-U-CE-R10
KINO-TGL-U-i3-R10
KINO-TGL-U-i5-R10
KINO-TGL-U-i7-R10
NANO-ADL-P-CC-R10
NANO-ADL-P-i3C-R10
NANO-ADL-P-i5C-R10
NANO-ADL-P-i7C-R10
WAFER-EHL-J6412C-R10

Affected by This Change

- | | | | |
|--|-------------------------------------|--|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input checked="" type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.