

Product Change Notification

Issue Date: Apr 01, 2023

Product Name: Mustang-M2BM-MX2-R30

Status: Running change

This notice is to inform you of changes to the Mustang-M2BM-MX2 series.

Reason for Change

Boost Converter CAT3200HU2-GT3 EOL
MLCC MURATA GRM033R60J105MEA2D shortage
Electronic Switch Nidec CVS-03TB shortage
OSC TXC 8W24000011 shortage
Buck converter TI TPS62095RGTR shortage
Load switch TI TPS22964CZPR shortage
Step-Down Converter TI TPS82085SILR shortage

Description of Change

Boost Converter CAT3200HU2-GT3 change to AIC AIC1848GGTR
MLCC MURATA GRM033R60J105MEA2D change to WALSIN 0201X105M6R3CT
Electronic Switch Nidec CVS-03TB change to Diptronics DHNF-02-T-Q-T/R
OSC TXC 8W24000011 change to AKER SMA-024000-2BY4T0
Buck converter TI TPS62095RGTR change to JOULWATT JW5255ADFN#TR
Load switch TI TPS22964CZPR change to JOULWATT JW7111SDFNB#TRPBF
Step-Down Converter TI TPS82085SILR change to CYNTEC MUN3CAD03-SE

Affected Model

Affected Model	New Version
Mustang-M2BM-MX2-R20	Mustang-M2BM-MX2-R30

Affected by This Change

- | | | | |
|---|-------------------------------------|-------------------------------------|----------------------------------|
| <input type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details, please refer to the latest datasheet or visit <http://www.ieiworld.com>.

*Best Regards,
Ting
Product Manager
IEI Integration Corp.*