

Technical Notice

Issue Date: July 5, 2024

Product Name: PPC2-EHL

Implementation Date: July 5, 2024

This notice is to inform you of changes to the:PPC2-EHLSeries

Reason for Change

Intel® Ethernet Controller i225 Supply issues.

Description of Change

Change LAN IC from Intel® Ethernet Controller I225LM/I225V to Intel® Ethernet Controller I226LM/I226V

Affected Model

| Affected Model |
|--------------------------|
| PPC2-C08-EHL-J1/8G-R10 |
| PPC2-C10-EHL-J1/8G-R11 |
| PPC2-C12-EHL-J1/8G-R10 |
| PPC2-C15-EHL-J1/8G-R11 |
| PPC2-C17-EHL-J1/8G-R12 |
| PPC2-C19-EHL-J1/8G-R11 |
| PPC2-CW123-EHL-J1/8G-R10 |
| PPC2-CW133-EHL-J1/8G-R10 |
| PPC2-CW15-EHL-J1/8G-R11 |
| PPC2-CW19-EHL-J1/8G-R11 |
| PPC2-CW22-EHL-J1/8G-R11 |

Affected by This Change

- | | | | |
|--|-------------------------------------|--|----------------------------------|
| <input checked="" type="checkbox"/> Specifications | <input type="checkbox"/> Dimensions | <input type="checkbox"/> Appearance | <input type="checkbox"/> Package |
| <input type="checkbox"/> Certification | <input type="checkbox"/> Label | <input checked="" type="checkbox"/> BIOS | <input type="checkbox"/> Driver |

For more details please refer to the latest datasheet or visit <http://www.ieiworld.com>.

Best Regards,
IRIS Shi
Project Manager
IEI Integration Corp